United States Department of the Interior National Park Service

DT 146

National Register of Historic Places Registration Form

HD 84

Date of Action

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in Guidelines for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries. 1. Name of Property historic name PARADISE HISTORIC DISTRICT other names/site number 2. Location not for publication street & number MOUNT RAINIER NATIONAL PARK city, town vicinity county LEWIS: PIERCE code 041: 053 WA state WASHINGTON code zip code 3. Classification Category of Property Number of Resources within Property Ownership of Property private building(s) Contributing Noncontributing X district public-local buildings public-State site sites X public-Federal structure structures object objects Total lame of related multiple property listing: Number of contributing resources previously <u>Historic Resources of Mount Rainier</u> listed in the National Register _ National Park State/Federal Agency Certification As the designated authority under the National Historic Preservation Act of 1966, as amended, I hereby certify that this Inomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property meets does not meet the National Register criteria. See continuation sheet. Signature of certifying official Date State or Federal agency and bureau In my opinion, the property X meets does not meet the National Register criteria. L See continuation sheet. December 13. Signature of commenting or other official of Archaeology and Historic Preservation State of Federal agency and bureau 5. National Park Service Certification I, hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National Register. See continuation sheet. determined not eligible for the National Register. removed from the National Register. other, (explain:)

Signature of the Keeper

6. Function or Use	
Historic Functions (enter categories an instructions)	Current Function enter categories from instructions)
DOMESTIC/Hotel; Institutional Housing	DOMESTIC/Hotel: Institutional Housing
GOVERNMENT/Administrative Facilities	GOVERNMENT/Administrative Facilities
RECREATION AND CULTURE/Outdoor Recreation	RECREATION AND CULTURE/Gutdoor Recreation
THE OTHER THAN SOUTH THE STATE OF THE STATE	(
7. Description	
Architectural Classification	Materials (enter categories from instructions)
(enter categories from instructions)	
(foundation <u>Concrete</u> : Stone
OTHER-RUSTIC STYLE	walls _WOOD/Log;Shingle;Stone
OTHER-ROSTIC STILL	
	roof WOOD/Shingle
	other
	VIIIVI

Describe present and historic physical appearance.

The Tacoma firm of Heath, Grove and bell chosen by the Rainier National Park Company (RNPC) to design its first major concession structure—the Paradise Inn (1917)—produced a romantically eclectic building that harmonized well with its subalpine setting. The Inn's steeply-pitched roof, massive log framing, cedar shingled siding and roofing weathered to a silvery gray, and native stone masonry echo the colors and contours of the rugged terrain of Paradise Valley. Subsequent structures built by the RNPC and the National Park Service at Paradise continued in this theme, creating a subalpine variation of the Rustic Style in the park.

The steeply-pitched roofs used on the majority of structures at Paradise represent one alternative to dealing with Paradise's heavy snowloads. The reinforced concrete shallow-pitched roofs of the Comfort Station and the nearby Edith Chlorination House represent another. The tremendous strain placed on the structures at Paradise by snowfalls averaging 799+ inches/year has resulted in numerous repairs and alterations to the buildings over the years. Despite these changes, the cluster of structures around the Inn that forms the Paradise Historic District retains a high degree of integrity of design.

See the attached PNR Inventory Cards for more information regarding the buildings within the Paradise Historic District.

o .	:.
D □E □F □G	
Period of Significance 1916 - 1937	Significant Dates
sidered the gnificance of this property in relation to other perties: nationally	
Architect/Builder	
policable National Register Criteria	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Paradise Historic District is significant for its association with federal administration, management, and development of the national park (Criterion A). For most of the park's history, the area called Paradise was dominated by concession-built structures. The government did require a presence at Paradise, and in 1911 a ranger cabin (no longer extant) was built, later to be replaced by a ranger station (1921) which stands today as the oldest government building within the historic district. This building (P-001) was the first government-built structure in the park to have rock masonry walls.

The district is also significant for its architecture, expressed in an "Alpine-Style" variation of the Rustic (Criterion C). This style espoused the use of native materials, particularly wood and stone, to better blend manmade structures with the natural environment. Weathered logs and native boulders were incorporated into the design of the more prominent buildings in the district.

Overall, the Paradise Historic District is a visually cohesive complex of Rustic Style buildings which still convey their historical associations with tourism and recreation in the national park. The Paradise Inn was designated a National Historic Landmark in 1987.

Six buildings comprise the Paradise Historic District. See the attached PNR Inventory Cards for additional information regarding these buildings.


9. Major Bibliographical References	
SEE MULTIPLE PROPERTY DOCUMENTATION FORM	
	. (
• •	
	•
	•
	See continuation sheet
Previous documentation on file (NPS):	D: Landing of additional date.
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data: State historic preservation office
has been requested X previously listed in the National Register	Other State agency
previously determined eligible by the National Register	X Federal agency
X designated a National Historic Landmark	Local government
recorded by Historic American Buildings	University Other
Survey #	Specify repository:
Record #	
O Company Many Date	
Acreage of property Approximately 10 acres	
Acreage of property	(
UTM References	в 11 0 5 9 6 6 1 7 5 1 8 1 9 6 8
A 1, 0 5 9, 6 6, 4, 8 5, 1 8, 1 9, 7, 0 Zone Easting Northing	B 1, 0 5 9, 6 6, 1, 7 5, 1 8, 1 9, 6, 8 Zone Easting Northing
c 1, 0 [5 9, 6 5, 9, 1] [5, 1 8, 1 9, 7, 8]	D 11 0
	□ a d'austina abast
USGS Quad: Mount Rainier East, Washington 1:24,000	See continuation sheet
Verbal Boundary Description Starting at the junction	n of the service road to the Inn and the
narking lot, then generally westward along t	the north edge of the parking lot to a foot
trail west of the comfort station, then nort	thwest along that trall to a toot trall run-
ning northeast, then along that Tool trail	in a northeast direction to its junction with that foot trail to its junction with the ser-
wise read then northeast along the service	road to its end, then easterly to the park roa
that passes through Paradise Valley, then so	outhwest See continuation sheet along the park road
to the point of beginning. Boundary Justification	
-	Sisset biotomic buildings and some land
The boundary was drawn to include all signi- encompassing the structures in order to con	vev the historic setting.
encompassing the structures in order to con-	vey and moon to cooking.
	`
	See continuation sheet
44 Form Brogged By	
11. Form Prepared By name/title Stephanie Toothman, Ph.D, Chief, Cu	Iltural Resources Division
organization National Park Service, Pacific Nort street & number 83 S. King Street, Suite 212	hwest Regionate September 1983
street & number 83 S. King Street, Suite 212	telephone (206) 442-0791 state Washington zip code 98104
city or town <u>Seattle</u>	State nastring on Zip code Zip

PN 70 6/82		NA INVENTO	National Park Service Pacific Northwest Region Cultural Resources Division					2	lestin B 001 Siz eattle, \	="		
2 NAME(S) OF STRUCTURE			5 ORIGINAL USE	7. CLAS	SIFICATION		_	į				2. RATING
Paradise Ranger St	ation	•	Ranger Station/ Living Quarters			. 						10. DATE
3 SITE ADDRESS (STREET & NO)			6. PRESENT USE									1921
				a. UTM	ZONE EA	STING			NORTHING	<u></u>		11, REGION
Paradise P-001			Ranger Station		100					<u> </u>		
Paradise	COUNTY Pierce	Wa	state shington	SCALE	1:24 OTHER:	· .	1:62.5			QUAD NAME		
NPS/Mount Rainier NPS/Mount Rainier NPS/Mount Rainier Rescription and Background His important Builders, architects, is stone and timber fra and verges; stone choff center front doc exposed log ceiling. This stone and timber 1921 during the admit for the distinctive, Stephen T. Mather. Originally, the firs with bedroom, bathrough the winter of and kitchen facilitifire cache and works of the cedar shingles.	ing vinctubing construction of bigineers, etc. me; 1-1/2 stories; imney; cedar siding or composed of half joists; first floor frame building with instration of Supersteeply pitched got the measures 18' x at floor was operated on and kitchen. The 1970-71, water pitches were subsequent them constructed to the superstructed of the superstructed	rectange at gab logs; so ranger as designable roo 26' included as an an an armost removed the range pes frozens at 1930 at	ular plan; steeply le ends; full widt tone foundation; o station, second f ned to serve as th nt W.H. Peters, it f and rustic, rubb uding a front pore information and o r station was occu- e and burst with red and the upper f	-pitch h one ouble loor o e Para was o le mas h 6' w heckir pied s esulti loor v	ed cedar story st hung cas offices. dise Ran completed conry wal ride exter g station easonall ing damag was remoding, was a	shir one per a land ls wanding m; they, go to leled lso	ngle corch and C open as ap g the ne up enera the for	heck heck prove ful per lly living	ing Sor used by length floor from Ing quice sp1971	tation verior ve	. Cor 922. Service the i living rough . The A time	nstructed in The design the Director front facade g quarters October. the bathroom
14 CONDITION EXCELLER	и №000р	FAIR	DETERIORATED	☐ RUINS	15. D/	ANGER O	F DEMOLE	ITION?	YES	Пио	Ø۷	NKNOWN

largely unaltered. Steel bracing and cables attached to the chimney at the building's rear provides bracing for the structure during heavy winter snows.

Significance

Designed by the National Park Service, Landscape Engineering Division, the plans were approved by Stephen T. Mather in May 1921. Consideration of the building's constructed at Mount Rainier to employ an extensive amount of stone, the rubble masonry walls blend tastefully with the surrounding terrain. The impressive steeply pitched gable roof was built to withstand the large amounts of snowfall that occur at Paradise.



- Interview with Lee Henkle, NPS Seasonal Ranger, Paradise, Washington, 8/23/82.

- Building File P-001, Maintenance Division, Mount Rainier National Park, prepared by L.M. Moe 10/21/49; photo (no date).

- Superintendent's Monthly Report, 28 July, 1922, Archives, Mount Rainier National Park.

- Original Drawing, "Paradise Checking Station - Paradise Valley," 1 sheet, approved by Stephen T. Mather, National Park Service, 28 May, 1921.

- Erwin N. Thompson, Mount Rainier National Park, Washington - Historic Resource Study (Denver, CO, N.P.S., 1981).

- Robert L. Carper, List of Classified Structures Inventory, (Denver, CO, N.P.S., 1976).

•		
22 INVENTORIED BY	AFFILIATION	DATE
COTE	MORA Cultural Resource Survey	7/23/82
GGr	This cultural resource burvey	7723702

P/ 70 6/82	adise Comfort Station adise P-304 county adise P-304 county adise Pierce ADMIN ADDRESS //Mount Rainier National Park, Tahoma Wo introducting Architects engineers etc inforced concrete construction; I story; res and verges; stone chimney; stone ver elter; casement windows; concrete floor; s reinforced concrete building with a story indicate and person and person windows; concrete floor; s reinforced concrete building with a story and Design, Thomas C. Vint, Chief ed to harmonize with the sloping terrain cked from as far away as Ashford, were the of the stones were quarried from near cility until the 1929 season. In addition or averaged of the massive roof, designed or averaged. The massive roof, designed or averaged. Total expenditures for the	INVENT	RO	Pacific No		2001	1 Sixti	 91.			
2 NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLAS			1			1	~ "	2 RATING
2 NAME(3) OF STRUCTURE		5. 0.113.113.552				•			. 1	1	! ·
¥			1					\neg	\Box	1	10 DATE
Paradise Comfort Sta	tion	Restroom	<u></u>								
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE						}			1020 20
Paradise P-304 * CITY/VICINITY COUNTY STATE Paradise Pierce Washing OWNER/ADMIN ADDRESS NPS/Mount Rainier National Park, Tahoma Woods-State Discontinuous Anchitects, Engineers, Eric Reinforced concrete construction: 1 story; rectang Reinforced concrete construction: 1 story; rectang								<u></u>	<u> </u>	'	
		B	Pacific Northwest Region Cultural Resources Division Seattle, Washington 98121 TOOM TOSE 1928-29 TOOM SCALE 124 OTHER OTHER ROULE, Ashford, Washington 98304 S. MAIEDIALS, MAJOR ALLERATIONS, EXTANT EQUIPMENT, AND Lar plan; low pitch, reinforced concrete gable roof with projecting for; entrances at north and south facades, one with timber lean-to foundation. Per serves as a confort station at Paradise. It was erected in 1928 the comfort station was designed by the NPS Western Region, Branch to The low pitched gable roof and random stone facing were compacent buildings. Construction began in July of 1928. Materials, ayed on portions of the Nisqually Road undergoing reconstruction are than anticipated hauling costs delayed the opening of the for installing a slate roof over the 6" reinforced concrete slab tand snow loads of 35 pcf to a depth of 35', was simply tarred								
Paradise P-304		Restroom				<u></u>	<u> </u>	ىلىك			62
		state Washington	SCALE		1:62.5						
Reinforced concrete eaves and verges; st shelter; casement wi This reinforced conc by the National Park of Plans and Design, bined to harmonize we trucked from as far Some of the stones we facility until the l	construction; 1 store one chimney; stone one chimney construction of the construction of t	ry; rectangular plan; leveneer exterior; entraror; concrete foundation a stone veneer serves a g 26' x 36' the comfortief Architect. The lower ain and adjacent building often delayed on posearby. Higher than antition, plans for instal	ow pitoles at a constant of the constant of th	nfort state on was desired gable reconstruct of the Nised hauling slate roce	cion at lesigned by coof and cion begandly by costs of over	Para y the ran an i Road dela the	dise ne NP: ndom s n Jui l unda nyed t	one To Westone Stone Stone	with was stern fac 1920 ing re openin	ere Reg ing 8. econ ng o	cted in 1928 tion, Branch were com- Materials, astruction. of the
were scrapped. The and graveled. Total and the interior wal	massive roof, desig expenditures for t ls refinished with	ned to withstand snow 1	.oads o > \$6.40	f 35 pcf t O. New fi	to a depi Extures l	th o have	of 35 rece	', wa ently	as sir 7 beea	mply n in	tarred stalled

E CICNICICANCE

14 CONDITION

EXCELLENT

⊠GOOD

FAIR

Designed by the NPS, Western Region, Branch of Plans and Design in San Francisco with Thomas C. Vint, Chief Architect, this comfort station, constructed with reinforced concrete, marks a significant departure from the standard stone and timber materials used to build other restroom facilities in the park. The massiveness was required for the heavy snowfalls that occur at Paradise. The stone veneer and low pitched gable roof were employed to blend the building in with the surrounding terrain.

□ RUINS


DETERIORATED


15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

□N0

Мпикиоми









18. LOCATED IN AN HISTORIC D	ISTRICT?	YES	MO	NAME			 				.	_
19 PUBLIC ACCESSIBILITY	YES, LIM	TED 5	YES, UNLIM	ITED	EXISTING SURVEYS	COUNTY	 HABS	HAER-1	HAER	⊠ NPS	STATE	_

21. REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building File P-304; Maintenance Division, Mount Rainier National Park; Waterhouse Report on Construction Activities (with photos), 1928.

Original Drawing "Comfort Station - Paradise," 1 sheet, recommended by Thomas C. Vint, NPS, 5/23/28 (DRG No.), Drawings and Document File, Maintenance Division, Mount Rainier National Park.


Robert L. Carper, List of Classified Structures Inventory (Denver, Colorado: NPS, 1976).

		
22 INVENTORIED BY	AFFILIATION	DATE
22 Intervious B.		l 7/23/82
CGF	MORA Cultural Resource Survey	1143/04
- Car	<u> </u>	<u> </u>

PF 70 6/82		NRO	National Park Service Pacific Northwest Regic Cultural Resources Divis	on 2001 Six	Westin Building, F 2001 Sixth Avera Seattle, Washington				
2 NAME(S) OF STRUCTURE	<u> </u>	5. ORIGINAL USE 7	CLASSIFICATION			2 RATING			
		·				10 DATE			
Paradise Ski-Tow Po	owerhouse	Ski-Tow Powerhse.] IO DATE			
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE				1937			
:]		<u></u>	<u> </u>	<u> </u>			
	·		UTM ZONE EASTING	NORTHING	196.00	11. REGION			
Paradise P-514		Storage Shed			7.				
4 CITY/VICINITY	COUNTY		CALE 1'24 1 62.5	QUAD					
Paradise	Pierce	Washington	OTHER	NAME					
Timber A-frame; 1 1, siding under gable e second floor access concrete blocks. During the 1930's, I were permitted in the about 12' x 14' and	Paradise Valley developed national parks, the CO was designed to blend wirum were housed in the ground were housed in the ground parks and the ground were housed in the ground runn runn were housed in the ground runn runn runn runn runn runn runn r	lan; steeply pitched of siding on north and ound floor contains me into a major northwest constructed a portal the nearby Guide Ho	edar shingle gable roo south facades; cedar sh stor for ski-tow; wood s at ski center. As no pe sle ski-tow in 1937. The suse and Paradise Ranger	ringle siding kid foundation with the control of th	to the n resti ift fac ame mea	rear; ng on ilities sured			

16. SIGNIFICANCE

The Ski-Tow Powerhouse was built by the CCC in 1937 as winter skiing in Paradise Valley reached its peak. It was built to blend with the nearby Cuide House and Paradise Ranger Station (the steeply-pitched, cedar-shingled gable roof with vertical board-and-batten siding under the gable ends was nearly identical to the Ranger Station's original appearance). The Ski-Tow Powerhouse remains from this era, largely unaltered.



21. REFERENCES—HISTORICAL REFERENCES. PERSONAL CONTACTS, AND/OR OTHER
Building File P-514, Maintenance Division, Mount Rainier National Park; photographs (undated).

Erwin N. Thompson, Mount Rainier National Park, Washington: Historic Resource Study, (Denver, CO: NPS, 1981) p.85.


Arthur D. Martinson, 'Mountain in the Sky: A History of Mount Rainier National Park" Phd. dissertation, Washington State University, 1966, pp.106-112.

-4.

70 6/82			Pacif	nal Park Service ic Northwest Reg ral Resources Div	ion 200	stin Bui 01 Sixt	1920	
	<u> </u>	5. ORIGINAL USE	7. CLASSIFICATION	101103001003 D14	ISION See	1110, ***	asi iii giloi	9. RATING
NAME(S) OF STRUCTURE		S. SHIGHNAL GOL	r. densamonto.		•	1	1 1 1	
	(CARD 1 of 3)							10. DATE
Paradise Inn	•	Resort Hotel				<u> </u>		
SITE ADDRESS (STREET & NO)		6, PRESENT USE	****			1 1		1017
		· ·	·			<u> </u>	<u> </u>	1917
		D 11 17-4 1	B. UTM ZONE	EASTING	NORTHING		19300	11. REGION
Paradise P-600	1	Resort Hotel						
CITY/VICINITY	COUNTY	STATE	SCALE 1:2	1:62.5	QU	AD		
Paradise	Pierce	Washington	01	HER ·	NAI	<u> 16</u>		
projecting eaves and hung sashes; glass de foundation: three wi	verges; gable and ouble doors entrand ngs-lobby, dining a	story; modified T-shape shed dormers; stone chir es into lobby; wood floo and hotel; kitchen wing exterior buttresses rep	mneys; cedar ors; exposed remodeled c.	shingle exte whole log fra 1930; gift sho	erior wall ame in lob op formed	s; nu by; n	merous ubble m	double asonry
structed in 1916-17 of the fledgling Nat cession enterprise i	under the auspices ional Park Service, n the park. Mather	ort hotel located in the of the Rainier National brought together busine believed such a dominer took the erection of a le	Park Compan essmen from nt company w	y. In 1916, S Seattle and Ta as needed to u	Stephen T. acoma to f upgrade vi	Math orm a sitor	er, dir large servic	ector con- es .
The site for the Inn	had been hurridly	leath,Grove and Bell of ' selected and surveyed. the Clouds." They had p	During the	Inn's construc	ction the	Raini	er Nati	onal
14 CONDITION EXCELLENT	[] [6000 [FAIR DETERIORATED	RUINS	15, DANGER OF DEMOLITIC	N7 TES	Пио	M nukuc	WN .

SIGNIFICANCE

The Paradise Inn was the first permanent resort hotel erected in a subalpine area in Mount Rainier National Park. Visitation to Paradise Valley and the Inn increased dramatically upon completion of the structure in 1917. The Rainier National Park Company (formed with the support of Stephen T. Mather), one of the early park concessionnaires built and operated the Inn. Their subsequent expansion of visitor facilities can be attributed to the success of the resort hotel. It is an architecturally distinct structure modeled after the Swiss alpine lodges. Native Alaska cedar was used in its construction. The lobby wing, containing exposed whole log trusses, posts and beams is particularly distinctive. Two large stone fireplaces and handcrafted tables, chairs and benches of Alaska cedar are located in the lobby. The Inn's exterior, covered with cedar shingles and containing numerous gable and shed dormers, is slightly altered. Original exterior, whole log trim around doors and windows has been partially removed. New



18 LOCATED IN AN HISTORIC DISTRICT? YES NO NAME

19. PUBLIC ACCESSIBILITY YES, LIMITED YES, UNLIMITED 20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE SURVEYS COUNTY LOCAL OTHER

Building File P-600, Maintenance Division, Mount Rainier National Park; sketch plan of roof, 1/75.

Erwin N. Thompson, Mount Rainier National Park, Washington: Historic Resource Study, (Denver, CO: NPS, 1981) pp.77-92.

Robert L. Carper, List of Classified Structures Inventory, (Denver, CO: NPS, 1976).

Superintendent's Monthly Report, 4 June 1925, Archives, Mount Rainier National Park.

Robert N. McIntyre, "Short History of Mount Rainier National Park" (1952), unpublished manuscript, Archives, Mount Rainier National Park p.227 and 230.

Paul H. Sceva, "Recollections by the Old Man of the Mountain," reproduced by the author, 1974, Archives, Mount

Rainier National Park !

22. INVENTORIED BY

GGF | AFFILIATION | DATE | 7/23/82

n' 9 6/82	NF	National Park Service Pacific Northwest Region					tin Building, F 1920 1 Sixth Aven				
Site I.D. NO		IÑ√ENT	ORY	Cultural R		_		Seatt	le, Wa	shingt	on 98121
NAME(S) OF STRUCTURE	(CARD 2 of 3)	5. ORIGINAL USE	7, CLAS	SIFICATION							2. RATING
Paradise Inn		Resort Hotel									10. DATE
SITE ADDRESS (STREET & NO)		6. PRESENT USE			•						1917
	,	Resort Hotel	8, UTM		TING	-1 1	NORTI	HING		1 18	11, REGION
Paradise P-600		<u>. l</u>		100 444		Ш.,			<u> </u>		8
CITY/VICINITY	COUNTY Pierce	siate Washington	SCALE	I:24 OTHER:	1:6	2.5		QUAD NAME			
Paradise OWNER/ADMIN ADDRESS	TTCTCC	Habitati Beott	<u> </u>					·			
- · · · · · · · · · · · · · · · · · · ·	sect a first mater tree	1- Ch Davies A-1	.e								
NPS/Mount Rainier	National Park, Tahoma Wood	<u>us-Star Koute, Asr</u>	irora, V	vasningtoi	<u> </u>						
DESCRIPTION AND BACKGROUND HIS	TORY INCLUDING CONSTRUCTION DATE(S), PHYSIC ENGINEERS, ETC.	OLAM, ZJAIPĒTAM, SKOISKAMIG. JA	R ALTERATIO	NS, EXTANT EQUIP	MENT, AND						
IMPORTANT BUILDERS, ARCHITECTS, I	ENGINEERS, ETG.										
to Mather, unsight cedar, was gathere in July 1, 1917.	ly arrangement of tents end from a nearby silver for	xisting in Paradis rest (a fire swept	e Valle area)	ey. Timbe . The res	er for sort h	the I otel w	nn, as o	compr: pened	ised for	of Al busin	aska ess
room (50' x 100')	easuring 50' x 112') contain containing a kitchen wing rooms. A three story win lets, a second floor with	(38' x 40'). Loc ng off the rear of	ated al	ove the c ining area	lining aand	area lobby	on t cont	he se ained	cond : a g	round round	were floor
rooms." The Inn w	was immediately successful os. In 1920, the Rainier	. Visitors prefer National Park Comp	red the any ere	e more rei ected an a	Fined additi	sleepi on to	ng a the	ecomm Inn ka	odati nown	ions r as th	ather e Annex
(see entry of Para	dise Inn Annex P-602). In the road from Longmire to	n 1925, a mezzanir o Paradise in the	ne leve. twenti	L was adde es. visita	ed aro ation	und th to the	e Io : Inn	bby's furtl	inte her i	rior. Increa	With sed.
A complex of 215 f	rame cabins was construc	ted nearby in 1930	replac	cing the d	old te	nt can	τρ.	The Pa	aradi	lse Lo	dge
built in 1931 prov	rided services for the cab ever, continued to operate	ins and for the fi	rst tir md 1939	ne, visito 5 Paul 9	or iac Sceva	oener oener	s op	ened j	year r of	the R	. ine ainier(co
raradise inn. nowe	ever, continued to operate	seasonarry. MICC	はい エンフ・	/ 1 <u>W</u> 44 1	veva,	ACT ICL	ااالدما	<u></u>			

DETERIORATED

16 SIGNIFICANCE

14 CONDITION

EXCELLENT

steel teebeam buttresses encased in logs have replaced the original.

FAIR

G000


...

RUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) YES

□ио

Пикиоми







18 LOCATED IN AN HISTORIC	DISTRICT?	s	JNAME							
19 PUBLIC ACCESSIBILITY	YES, LIMITED	YES, UNLIMITED		20. EXISTING SURVEYS	COUNTY	NHL HABS	HAER-1 OTHER	☐ HAER	NPS	STATE
19 PUBLIC ACCESSIBILITY YES, LIMITED YES, UNLIMITED 20. EXISTING NR NHL HABS HAER-1 HAER NPS STATE										
				•						
			-				•			
•						•				
9 PUBLIC ACCESSIBILITY YES, LIMITED YES, UNLIMITED 20. EXISTING NR NHL HABS HAER-1 HAER NPS STA SURVEYS COUNTY LOCAL OTHER 21 REFERENCES- HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER										
22 INVENTORIED BY				AFFILIATION				DATE		
		•						- 1		

Pr 70 6/82		NE	National Park Service Pacific Northwest Reg	
1. Site I.D. NO		IN VENT	ORY Cultural Resources Div	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
7 NAME(S) OF STRUCTURE		5. ORIGINAL USE	7 CLASSIFICATION	2. RATING
Paradise Inn	(CARD 3 of 3)	Resort Hotel		10. DATE
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE		1917
Paradise P-600		Resort Hotel	6. UTM ZONE EASTING	NORTHING 11, REGION
· city/viciNity Paradise	county Pierce	state Washington	SCALE 1:24 1:62.5 OTHER:	QUAO NAME
12. OWNER/ADMIN ADDRESS	National Park, Tahoma	Woods-Star Route Ashi	ord Washington	
TO SCRIPTION AND BACKGROUND I	HISTORY INCLUDING CONSTRUCTION DATE(S). 5, ENGINEERS, ETC	PHYSICAL DIMENSIONS, MATERIALS, MAJOR	ALTERATIONS, EXTANT EQUIPMENT, AND	
National Park Com	pany, ordered the demol	ition of the original		placed with a new, larger one. a gift shop.
cabins never provide to inadequate method in the NPS. The NPS next decade incluin the kitchen. was expressed by removal of the Invailed. In 1980, new sprinkler sysin half logs. Ti	red to be popular, and we waintenance. In 1952, to thereupon leased the I ding miscellaneous shin Despite the repairs, dithe public, government on and conversion of Par removation to improve tem was installed. The e rods were installed to	re sold as defense hou he financially ailing nn to the concessionne gling and painting. A ssatisfaction with the officials and concessi adise into a day use a the fire safety and l existing whole log bu hroughout the lobby's	using in 1942. The Inn de Rainier National Park Com hire. Various maintenance additionally, an employees Inn's condition and visition Connaires. The 'Mission 6 hrea only. Public pressur Cobby's structural stabili	cafeteria was installed tor facilities at Paradise of" program called for the re to retain the Inn pre- ty were carried out. A th steel tee beams encased date, exterior whole log

DOMESTICATION OF THE PROPERTY OF THE PROPERTY

14 CONDITION

The Inn continues to retain its original exterior lines and the lobby interior remains largely unaltered. Guest Services Incorporated currently operates the tun on a seasonal basis.

RUINS

DETERIORATED

Пликиоми

15. DANGER OF DEMOLITION? (SPECIFY THREAT)

YES

□ио

The Paradise Inn was designated a National Historic Landmark in 1987.

FAIR

GOOD

EXCELLENT

17. PHOTOS AND SKETCH MAP OF LOCATION

18 LOCATED IN AN HISTORIC DISTRICT?





LOCATED IN AN HISTORIC	DISTRICT? YES	NO DIAME							
PUBLIC ACCESSIBILITY	YES, LIMITED	YES, UNLIMITED UNKNOWN	20. EXISTING SURVEYS	OUNTY	HL DHABS	HAER-1	HAER	NPS	STATE
E REFERENCESHISTORICA	L REFERENCES, PERSON	VAL CONTACTS, AND/OR OTHER							
									•
•		i							
2. INVENTORIED BY	,	· · · · · · · · · · · · · · · · · · ·	AFFILIATION	<u></u>			DATE		
		,	<u> </u>		·		_L		

P' \(\) 6/82				N	30	Nationa Pacific	20	estin E 101 Si	er.	1920									
1. SITE I.D. NO									INVENT	ORY	Cuttura	al Res	ources Div	/ision	Se	attle,	Washir	ngtor	98121
2 NAME(S) OF STRUCTURE	L:	 .		T					5. ORIGINAL USE	7. CLAS	SSIFICATION			-1				.	9, RATING
															_,	$\dashv \neg \dashv$	 	1 1	10. DATE
Annex to the F	arad	ise :	Inn					_	Hotel					·-				igsquare	
3 SITE ADDRESS (STREET & NO)		-						-	6. PRESENT USE	7								1	1920
										<u></u>				1					11. REGION
										8. UTA	ZONE	EASTIN	G T	INC	PRTHING		1		TI, REGION
Paradise P-601									Hotel					L_		Ц.,		-	
4 CITY/VICINITY				-	MIY				STATE	SCALE			1.62 5			UAD			
Paradise				<u>Pie</u>	erce	<u> </u>			Washington		OTHE	Р			N	AME			
12. OWNER/ADMIN ADDRESS																			
NPS/Mount Rain	ier l	Natio	mal,	<u>Pi</u>	≀rk,	Ta	lhon	a Wo	ods-Star Route, As	hford.	Washing	ton_	98304						
13 DESCRIPTION AND BACKGROU IMPORTANT BUILDERS, ARCHIT	IND HISTO ECTS, EN	ONY INC	LUDING S, ETC.	CON	STRUC	CTION	DATE(S), PHY	COL DIMENSIONS, MATERIALS, MAJ	OR ALTERATIO	ONS, EXTANT ÉC	JUIPMEN	IT, AND						
gables; shed dor walls and ceilin	mers lgs (; prodoubl	ojec le - h	tir ung	ig e g sa	ave ishe	s a s;	nd v entr	ectangular plan; s erges; cedar-shing ance to annex by m central pavillion	led ext eans of	erior; timber	inte bri	rior con dge walk	tain way	ing w (late	ood 1 : 1920	Floor)'s);	, fi	nished
the inn was orig camp facilities. To accommodate t the east wing of architect Harlan was to be over 3	inall The the pu the Thor 00' ng of	ly co e inr ublic inn mas. long f the	nst in in to Or and	ruc iti des the igi co n	ted lall sire an lnal onta Th	l in y c fo nex in e s	ont r p ans a t	16, aine riva The cal alle ler	in 1920 under the it was believed the donly a few rooms te rooms with bath three-and-one-half led for a larger and central pavilliowings to either si	at visi , none s, the story nd gra n made de of t	tors won of which annex wa timber-: under st of stone	uld (h had as b fram truc e. '	continue d indiviouilt. A e buildi ture tha The cent	to dual noping was a war war war war war war war war war a w	use t bath en br as de s act pavil	he ex room idge signe ually lion	mande facil conne d by buil was t	ed t liti ecte Sea lt. to c	ent es. d ttle It onnect

15 SIGNIFICANCE

14 CONDITION

- EXCELLENT

Though original plans for the annex to the Paradise Inn called for a much larger building with a central stone pavillion and two timber-frame wings, only a portion was erected. The annex, completed in 1920, was linked to the inn with a timber-frame walkway. The building contains a distinctive steeply-pitched roof with intersecting gables.

RUINS

DETERIORATED

MONKNOWN


15. DANGER OF DEMOLITION? (SPECIFY THREAT)

steeply-pitched roof with intersecting gables and numerous shed dormers.

☐G000

⊠ FAIR

The annex measures approximately 44' x 125'. It continues to function as a hotel facility. In the late twenties a 'bermanent' enclosed walkway was built between the inn and the annex. Manager Paul Sceva supervised the construction.



Пинкноми 21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

TYES, LIMITED

19. PUBLIC ACCESSIBILITY

[]YES

ОМ

YES, UNLIMITED

Building File P-602, Maintenance Division, Mount Rainier National Park.

NAME

Paul H. Sceva, Recollections by "The Old Man of the Mountain," 1972, Archives, Mount Rainier National Park, pp.137-41.

20. EXISTING SURVEYS

NHL

LOCAL

NR

COUNTY

HABS

__HAER-1

OTHER

HAER

₹NPS

STATE

Erwin N. Thompson, Mount Rainier National Park, Washington: Historic Resource Study, (Denver, CO: NPS, 1981) p.82 & 89.


David E. Snow, Mount Rainier Paradise Inn: Historic Structure Report, (Denver, CO: NPS, 1979), pp.32-34 & p.142 (historic drawings).

Robert L. Carper, List of Classified Structures Inventory, (Denver, CO: NPS, 1976).

22 INVENTORIED BY	AFFILIATION	DATE
•• ••• •• •• ••		7/00/00
CCF	MORA Cultural Resource Survey	1 //23/82
GGI	12:11 002:02:01	

SITE I.D. NO		INVENT		ational Park Service acific Northwest Regio ultural Resources Divis	n 20	stin Bui 01 Sixti	n Aven.	1920 on 98121
NAME(S) OF STRUCTURE Paradise Guide House		s original use Mountain Climber's Guide House	7. CLASSIFICA					2 RATING
SITE ADDRESS (STREET & NO)		6. PRESENT USE						c. 1920
Paradise P-602	•	Dormitory and Guide House	8. UTM ZONE	EASTING	NORTHING			II. REGION
CITY/VICINITY Paradise OWNER/ADMIN ADDRESS	COUNIY Pierce	STATE Washington	SCALE	1:24 1:62.5 OTHER		JAD ME		
chimney; shed dormers and sliding glass wind	; cedar shingle sid dows; wood floors; lding was erected c Paradise Valley (1	lan; steeply pitched, ing and exposed whole stone masonry and cond .1920 by the Rainier P. 916-1920). Measuring oof, the only one of the windows lends a log	rete foun Tational P 32'-0" x	veneer; front cent dation. ark Company during 74' x 4", the timb	er entra g their i	initial e build	L expai	nsion of

The Guide House was originally erected by the Rainier National Park Company c.1920 during their early expansion of visitor facilities in Paradise Valley. It has been continuously associated with climbing expeditions of Mount Rainier. The building's gambrel roof is the only one of its kind in the park.



Building File P-602, Maintenance Division, Mount Rainier National Park; Sketch Plan; photo dated 1962.

Robert N. McIntyre, "Short History of Mount Rainier National Park" (1952) unpublished manuscript, Archives, Mount Rainier National Park, p.23.


Robert L. Carper, List of Classified Structures Inventory (Denver, Colorado: NPS, 1976).

Erwin N. Thompson, Mount Rainier National Park, Washington: Historical Resource Study (Denver, Colorado: NPS, 1981).

GGF

AFFILIATION MORA Cultural Resource Survey

OATE 7/23/82



Nos. #1-6 on map refer to Photo List # (See PHOTOS section)

HISTORIC BASE MAP

PARADISE HISTORIC DISTRICT
MOUNT RAINIER NATIONAL PARK

UNITED STATES DEPARTMENT OF THE INTERIOR/NATIONAL PARK SERVICE

105 28,001 DSC AUG 197

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

ction number	Page		
	SUPPLI	EMENTARY LISTI	NG RECORD
NRIS Refere	nce Number:	91000174	Date Listed: 3/13/91
<u>Paradise Hi</u> Property Na	<u>storic Distri</u> me	ct <u>Pierce</u> County	<u>WA</u> State
<u>Historic Re</u> Multiple Na		unt Rainier No	ational Park
Places in a subject to notwithstan	ccordance wit	h the attached exceptions, conal Park Serv	al Register of Historic d nomination documentation exclusions, or amendments, vice certification include
<u>Qubwictti 4-</u> signature c	f the Keeper		3/13/41 Date of Action
Amended Ite	ms in Nominat	=========== :ion:	=======================================
be amended	ion: The Num to read: one ributing reso	noncontribut	ces within Property should ing building and a total o
This inform Pacific Nor	ation was con thwest Region	afirmed with S hal Office NPS	tephanie Toothman of the
DISTRIBUTION Nation Nomina	al Register p	property file	mination attachment)